

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interposition ID: N/A	Main St			Cross	Stract	N/A			Location	N	
Intersection ID: N/A	Main Street: INDEPENDENCE_RD			Cross	Street:	N/A	Location:	N			
ADA ID: 2705629B056C	Ramp Type: Directional1			Initial	Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	10.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	0010	Possible Solutions:			Compliance Description Data			Comp	Compliance Description		
		Remove & Replace Enti	re Ran	np.	N/A	Ramp Length (in)	67.0	No	Grade Break?	No	
	See.			-	Yes	Ramp Width (in)	72.0	N/A	Grade Break Slope (%)	2.9	
A Carlos Carlos	2.5				Yes	Ramp Slope (%)	3.1	N/A	Grade Break XSlope (%)	2.2	
	2				No	Ramp XSlope (%)	2.3				
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	- 8 pm				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	CP. ///	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	1. 1.	N/A			Yes	Landing Length (in)	72.0	No	DWS Provided?	No	
	E NE				Yes	Landing Width (in)	72.0	N/A	DWS Contrast?	No	
	1.5.				No	Landing Slope (%)	2.3	N/A	DWS Length (in)	N/A	
	10 /				No	Landing X Slope (%)	2.4	N/A	DWS Full Width?	No	
	R	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	1 184	R304.5.3, R304.2.2-Perp	, R304	.3.2-	N/A	Shared Landing?	No	N/A	DWS Offset RT (in)	N/A	
		Para, R304.5.2, R305	-		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.3	
	11 March	`			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.3	
					N/A	Painted X Walk1?	No		Road Slope (%)	0.6	
Street 1 Name	ENTRANCE					X Walk 1 Direction	To SE		Road X Slope (%)	1.1	
Stop Condition-Street 1	None					X Walk 1 Width (in)	N/A		Clear Space?	Yes	
Street 2 Name	N/A					X Walk 1 Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	1.1	Yes	Storm Grate/Utility Hazard?	No	
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					Yes	Any Obstructions?	No			N/A	
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	9.6	

