cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29163	Main Street: FIRESTREAK_DR			Cross Street: CLAIBORNE_WOODS_RD				Location:	NW
ADA ID: 2838255DB02C	Ramp Type: BlendTrans1			nitial Pass/Fail: Pass Overall Compliance: No				o Severity Score	: 10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
ADVOCATOR LN		Possible Solutions:		Compliance Description		Data Compliance Description			Data
the second secon		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	47.0	Yes	BlendTrans Slope (%)	5.0
		Two New Directional Ramps o		Yes	Ramp Width (in)	59.0	Yes	BlendTrans XSlope (%)	0.9
		Equivalent.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
				N/A	Flare Slope LT (%)	4.3	Yes	Flare Slope RT (%)	2.7
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes
				Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
		Surveyor Notes:		Yes	Landing Width (in)	59.0	Yes	DWS Contrast?	Yes
		N/A		Yes	Landing Slope (%)	2.0	Yes	DWS Length (in)	24.0
				Yes	Landing X Slope (%)	0.7	No	DWS Full Width?	No
				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	7.5
				N/A	Shared Landing?	No			
All the second	A MEDIA	PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.4
	-	Not Found, R305.1.4, R305.2,		No	Gutter Lip Ht (in)	0.3	Yes	Gutter X Slope (%)	1.4
		R302.7.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	· Contraction				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
	Am A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	FIRESTREAK DR	-			X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.7		Clear Space?	Yes
					Road X Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

8.6