

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: WEST_BV			Cross	Street:	HOLABIRD_LN	Location:	NE		
ADA ID: 285450AFF905	Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	58.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	TO SA A	Possible Solutions:						Data Compliance Description		
		Remove & Replace Entire	Ram	D .	N/A	Ramp Length (in)	36.0	N/A	Grade Break?	N/A
The set of	an Car			. .	No	Ramp Width (in)	40.0	N/A	Grade Break Slope (%)	0.0
E					No	Ramp Slope (%)	15.1	N/A	Grade Break XSlope (%)	0.0
E en se	Martin State				No	Ramp XSlope (%)	7.9			
	Tate 4				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E SAN EST					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
B	/	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the the	-	N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
5 MESTEN	1 mil				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
a due	1				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	·/				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	Y	R304.5.1, R304.2.2, R304	.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	ALC: N	·····,····,·····,·····,·····,·····			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	a Maria				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	- ATA				N/A	Painted X Walk1?	No		Road Slope (%)	0.5
Street 1 Name HO	LABIRD LN					X Walk 1 Direction	To W		Road X Slope (%)	4.8
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	4.8	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	N/A	Curb Slope (%)	8.3

