## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46785	Main Sti	Main Street: DOMINION_VILLAGE_DR			Cross Street: AUTUMN_HARVEST_LN				Location:	E
ADA ID: 28D8CF3EF80	D: 28D8CF3EF801 Ramp Type: BlendTrans1				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
1100011		Possible Solutions:			Compliance Description Data			Comp	Compliance Description	
11 and 1		Remove & Replace Cu Two New Directional R Equivalent.	Curb Ram	p With	N/A	Ramp Length (in)	50.0	Yes	BlendTrans Slope (%)	3.9
			al Ramps or	•	No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	7.1
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1 LOCAL				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A SA	COLL VILLE				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			1, R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	DOMINION VILLAGE DR					X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	2.2
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	3.0
Street 2 Name	AUTUMN HARVEST LN				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	5.6		Clear Space?	N/A
						Road X Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.8