cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14851	ntersection ID: 14851 Main Street: E_WORTHINGTON_AV			Cross Street: PARK_RD				Location:	W
ADA ID: 2A411D3464D1	A ID: 2A411D3464D1 Ramp Type: BlendTrans1				nitial Pass/Fail: Fail Overall Compliance: No				1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A. A.S. A.	Possible Solutions:		Compliance Description Data Compli			liance Description	Data	
	\$1/	Remove & Replace Curb R	amp With	N/A	Ramp Length (in)	113.0	Yes	BlendTrans Slope (%)	4.7
		Two New Directional Ramp	•	Yes	Ramp Width (in)	58.0	No	BlendTrans XSlope (%)	2.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A SHOW	11/ 1/			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Store Par				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
The second second	a production	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second second	<u>6</u>	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
PROW/ADA: Not Found, R304.5.3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name E	E WORTHINGTON AV				X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	3.1		Clear Space?	N/A
					Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.6