

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47852Main Street: CACTUS_VALLEY_RDCross Street: STONE_PORCH_RDLocation:NEADA ID: 2A620506DA5ERamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	CACTUS VALLEY RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

1 OSSIDIE SOIGLIOII	
Possible Solutions:	c
Remove & Replace Entire Ramp.	
•	N
	N/
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1	N
•	N
	N
	N

ma leg	zriA l	

Total Cost:



1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	47.5	Yes	Ramp	Slope (%)	7.0	
No	Ramp Width (in)	47.0	Yes	Ramp	XSlope (%)	2.0	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A	
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	2.2		X Wa	lk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	1.9		X Wa	lk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A		Grate/Utility Hazard?	N/A	
	Obstruction Type				n Grate/Utility Type		
	, ,	N/A			, ,,	N/A	
			Yes	Surfa	ce Condition? (G/P)	Good	
					(-·)		