cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12213	213 Main Street: BELLE_TERRE_AV			Street:	KILGO_WY	Location:	NE		
ADA ID: 2B3F5D954367	7 Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Complia			liance Description	Data	
	\$ h	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	60.0	Yes	BlendTrans Slope (%)	2.0
		Two New Directional Ramps or	••••	No	Ramp Width (in)	43.0		BlendTrans XSlope (%)	0.3
		Equivalent.		N/A	Flare Type LT	N/A		Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
	at 1 and 1			N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
File and the second second				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
	Carl.	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	E JERRE AV			N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
		2		N/A	Shared Landing?	N/A		Dive enset (iii)	N/A
	2° line ton	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	6 7 7	Not Found, R304.5.1		N/A	Painted X Walk1?	N/A No	N/A	Painted X Walk2?	N/A No
				N/A	X Walk 1 Direction	To W	N/A	X Walk 2 Direction	To S
	turned the								10 S N/A
	9			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)		
Street 1 Name	KILGO WY				X Walk 1 Slope (%)	N/A		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	N/A		X Walk 2 X Slope (%)	N/A
Street 2 Name	BELLE TERRE AV			N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	1.6		Clear Space?	N/A
					Road X Slope (%)	3.6		Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

19.2