

Access Compliance Report Public Rights-of-Way (Curb Ramps)



				•	.					-	
Intersection ID: 13926	Main Street: PENCE_RD			Cross Street: VIOLA_DR				Location:	S		
ADA ID: 2B4295C8FF2C	Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	36.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
A STATE AND A STAT	a see the the	Possible Solutions:			Compliance Description Data Compliance				liance Description	Data	
The second s	e Jun Line	Remove & Replace Enti	re Ramp		N/A	Ramp Length (in)	70.5	Yes	Ramp Slope (%)	6.4	
MARCH AND AND	CARDEN Y		•		No	Ramp Width (in)	30.0	No	Ramp XSlope (%)	3.2	
The second second second	They to make				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	100	9			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
h	ALL THE FL	2			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
PENOR	and the second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	- +	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the state of the s		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	1				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	the second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
the store	A ANY A	9			N/A	Shared Landing?	N/A				
	The Burg	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1, R	304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	Jan Strange				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
A CALLER AND A CAL						X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
and the second second second	EL T				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PENCE RD					X Walk 1 Slope (%)	5.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	3.1	N/A	Clear Space?	N/A	
						Road X Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

Yes Surface Condition? (G/P)

Good

