cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: FALLOW_LN Cross Street: N/A									Location:	N
ADA ID: 2D1AD46A5980 Ramp Type: BlendTrans2			initiai	Pass/Fa			30			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	STURN CALL	Possible Solutions:			Compliance Description		Data Compliance		liance Description	Data
S AND		Remove & Replace Cur	•	p With	N/A	Ramp Length (in)	97.0	Yes	BlendTrans Slope (%)	1.5
		Two New Directional Ra		r	No	Ramp Width (in)	33.0	No	BlendTrans XSlope (%)	5.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and a start of the		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second secon		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
°C.	HIGH	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R	304 5	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	a contraction			•	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
35. 1 - 1					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
a ha ha					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	FALLOW LN					X Walk 1 Slope (%)	5.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	8.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	8.3		Clear Space?	N/A
						Road X Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	0.7 N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	¢	3200.00	11/2	Obstruction Type	17/4		Storm Grate/Utility Type	17/5
		10101 0051.	Ψ	3200.00			N/A		Storm Grate/Ounity Type	N/A
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

22.2