

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

32.0

42.5

7.1

0.1

8.6

7.8

N/A

No

To E

N/A

4.7

Intersection ID: N/A Main Street: BACK ACRE DR Cross Street: SAWMILL TRACE DR Location: NW 0 ADA ID: 2F293512006D Ramp Type: Combination1Diag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

Yes

Nο

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

30.0

44.0

9.8

1.8

51.5

34.0

N/A

No

To S

N/A

2.0



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

None **SAWMILL TRACE DR** StopSign **BACK ACRE DR** Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.1, R304.2.2, R304.5.3, R304.3.2

Total Cost:

Compliance Description N/A Ramp Length LT (in) No Ramp Width LT (in) No Ramp Slope LT (%) Ramp XSlope LT (%) Yes N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%)



X Walk 1 X Slope (%) 5.3 X Walk 2 X Slope (%) 3.3 N/A 3200.00 N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? N/A Road Slope (%) 1.5 Clear Space? N/A Road X Slope (%) 4.2 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 13.0 Curb Slope (%)



