cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 44071 Main Street: NEWLANDS_CORNER_LN | | | | Street: | SEDGEMOOR_LN | Location: | NE | | |
|--|----------------------------------|--|--------|--|-----------------------|-----------|-----------------------------|-----------------------------|-------|
| ADA ID: 30560807114 | 30560807114B Ramp Type: PerpDiag | | | itial Pass/Fail: Fail Overall Compliance: No | | | | Severity Score: | 55 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | |
| | | Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent. | Vith | N/A | Ramp Length (in) | 72.0 | No | Ramp Slope (%) | 9.2 |
| | | | - | No | Ramp Width (in) | 35.0 | No | Ramp XSlope (%) | 9.7 |
| | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| and the second s | It was to the first of | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | 1 2 4 | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| A SA | WEINE / | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| 8 | 6 | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| All and the second seco | CORVER S | 8 | | N/A | Shared Landing? | N/A | | | |
| | All all | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | CX III | Not Found, R304.5.1, R304.2.2, | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| <u>6</u> | | R304.5.3 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | N | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | To SW |
| d. | 1 2/20 | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | SEDGEMOOR LN | _ | | | X Walk 1 Slope (%) | 3.4 | | X Walk 2 Slope (%) | 1.1 |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 1.3 | | X Walk 2 X Slope (%) | 5.9 |
| Street 2 Name | NEWLANDS CORNER LN | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 4.3 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 4.3 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ 32 | 200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| 1 | | | | | | | l | | |

Yes Surface Condition? (G/P)

Good

