

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14366	Main Str	Main Street: E_KINGSTON_AV			WINTHROP_AV	Location:	N			
ADA ID: 3081A678A56A	Ramp Ty	Initial	Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score:		13.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Data Compl			liance Description	Data		
	St. TX	Remove & Replace Entire Ram	э.	N/A	Ramp Length (in)	84.0	N/A	Grade Break?	N/A	
and the second second	XIANX			Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
				No	Ramp Slope (%)	11.7	N/A	Grade Break XSlope (%)	0.0	
ALCONTACT A				No	Ramp XSlope (%)	3.4				
R R R		A		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A A A A A A A A A A A A A A A A A A A		A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
A CONTRACTOR OF THE PARTY OF TH		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
La	State -			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
the second secon	A A A	A		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
L L L	a start	A		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
AND AND AND	22010	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
Se / Jan A				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	81 41			N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A	
		A		N/A	Painted X Walk1?	No		Road Slope (%)	3.1	
Street 1 Name V	WINTHROP AV				X Walk 1 Direction	To SE		Road X Slope (%)	4.6	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.6	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	0.7	

