

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27041	Main Street: ENDHAVEN_LN			Cross Street: ORCHID_HILL_LN				Location:	NW	
ADA ID: 32D67AEC753A	AEC753A Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	1 1 1 1 1	Possible Solutions:		Compliance Description			Data Compliance Description			
a secondaria		Remove & Replace Entire Ram) .	N/A	Ramp Length (in)	84.0	N/A	Grade Break?	N/A	
				No	Ramp Width (in)	46.0	N/A	Grade Break Slope (%)	0.0	
	the gent			Yes	Ramp Slope (%)	6.7	N/A	Grade Break XSlope (%)	0.0	
	And a			Yes	Ramp XSlope (%)	3.4				
	The L			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	18th	1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	and the for	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
ANDRIAVAN INC.	a de la companya de l	NO LNDG		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
		*		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
A A A A A A A A A A A A A A A A A A A		14 A A A A A A A A A A A A A A A A A A A		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
A A A A A A A A A A A A A A A A A A A		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	R304.5.1		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
	5 5		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
			N/A	Painted X Walk1?	No		Road Slope (%)	1.6		
Street 1 Name E	NDHVEN LN	_			X Walk 1 Direction	To S		Road X Slope (%)	3.4	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.4	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	18.6	

