

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13561 Main Street: BAY ST **Cross Street: LAMAR AV** Location: **Overall Compliance: No ADA ID: 33CF3CCA86B8** Ramp Type: PerpDiag Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

4.2.2, R304.5.3

| 1000 | Doo |
|----------|------|
| 1 | R304 |
| - S | |
| | |
| | |
| BAY ST | |
| StopSign | |
| LAMAR AV | |
| StopSign | |
| | |
| | |
| | |

Total Cost:

| Comp | liance | Description | Data | Com | oliance | Description | Data |
|------|-----------------------|------------------|-------|-----|---------|-------------------------|-------|
| N/A | Ramp | Length (in) | 48.0 | No | Ramp | Slope (%) | 8.7 |
| Yes | Ramp | o Width (in) | 70.0 | No | Ramp | XSlope (%) | 3.8 |
| N/A | Flare | Type LT | N/A | N/A | Flare | Type RT | N/A |
| N/A | Flare | Slope LT (%) | N/A | N/A | Flare | Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | | N/A | N/A | Flare | Traversable RT? | N/A |
| N/A | Landi | ing Length (in) | N/A | N/A | DWS | Provided? | N/A |
| N/A | Landi | ing Width (in) | N/A | N/A | DWS | Contrast? | N/A |
| N/A | Landi | ing Slope (%) | N/A | N/A | DWS | Length (in) | N/A |
| N/A | Landi | ing X Slope (%) | N/A | N/A | DWS | Full Width? | N/A |
| N/A | Landi | ing Curb? (Y/N) | N/A | N/A | DWS | Offset (in) | N/A |
| N/A | Share | ed Landing? | N/A | | | | |
| N/A | Gutte | er Ponding? | Yes | N/A | Gutte | r Slope (%) | N/A |
| N/A | Gutte | er Lip Ht (in) | N/A | N/A | Gutte | r X Slope (%) | N/A |
| N/A | Paint | ed X Walk1? | No | N/A | Paint | ed X Walk2? | No |
| | X Wa | lk 1 Direction | To NE | | X Wa | lk 2 Direction | To NW |
| N/A | X Wa | lk 1 Width (in) | N/A | N/A | X Wa | lk 2 Width (in) | N/A |
| | X Wa | lk 1 Slope (%) | 4.6 | | X Wa | lk 2 Slope (%) | 2.6 |
| | X Wa | lk 1 X Slope (%) | 0.9 | | X Wa | lk 2 X Slope (%) | 3.4 |
| N/A | Ramp | inside XWalk1? | N/A | N/A | Ram | inside XWalk2? | N/A |
| | Road | Slope (%) | 3.5 | N/A | Clear | Space? | N/A |
| | Road | X Slope (%) | 6.7 | N/A | Clear | Space to XWalk (in) | N/A |
| N/A | Any (| Obstructions? | N/A | N/A | Storn | n Grate/Utility Hazard? | N/A |
| | Obstr | ruction Type | | | Storn | n Grate/Utility Type | |
| | | | N/A | | | | N/A |

Surface Condition? (G/P)

Good







3200.00