

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30360Main Street:TIMBERTOP_LNCross Street:WORLEY_DRLocation:NEADA ID: 3402A9DCA368Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WORLEY DR StopSign TIMBERTOP LN None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

rield Measurements/Component Compilance							
	Compl	Compliance Description		Compliance Description		Data	
	N/A	Ramp Length (in)	44.0	No	Ramp Slope (%)	9.3	
	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	4.0	
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
		X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	5.8		X Walk 2 Slope (%)	6.6	
		X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	7.7	
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
		Road Slope (%)	6.3	N/A	Clear Space?	N/A	
		Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A	
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Obstruction Type			Storm Grate/Utility Type		
		• •	N/A			N/A	
				I			

Yes

Surface Condition? (G/P)

Good





