

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10027867Main Street: HAMLIN_PARK_DRCross Street: N/ALocation:NEADA ID: 340B049CB7FFRamp Type: Directional1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 1.25

Codes/Mitigation Info/Possible Solution



Street 1 Name	ENTRANCE
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

0001010 001411011	
Possible Solutions:	Compli
Remove & Replace Entire Ramp.	N/A
·	Yes
	Yes
	No
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.5.3	N/A
	N/A
	N/A
	N/A

No.		
		が正常とう



Total Cost:



1600.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	101.0	N/A	Grade Break?	N/A	
Yes	Ramp Width (in)	96.0	N/A	Grade Break Slope (%)	0.0	
Yes	Ramp Slope (%)	5.9	N/A	Grade Break XSlope (%)	0.0	
No	Ramp XSlope (%)	2.6				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No		Road Slope (%)	1.3	
	X Walk 1 Direction	To NW		Road X Slope (%)	0.4	
	X Walk 1 Width (in)	N/A		Clear Space?	N/A	
	X Walk 1 Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A	
	X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A	
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
N/A	Any Obstructions?	N/A			N/A	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
		N/A	N/A	Curb Slope (%)	5.1	