

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10390	Main Str	Main Street: ENDERLY_RD			Cross Street: TUCKASEEGEE_RD				NE	
								Location:		
ADA ID: 3440FCD87218	ID: 3440FCD87218 Ramp Type: Directional1		Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	V AL MAR M	Possible Solutions:		Compliance Description			Data Compliance Description		Data	
	A AV Same	Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	49.5	N/A	Grade Break?	N/A	
and the second second	No Part	-		Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
	1-18-18			No	Ramp Slope (%)	11.0	N/A	Grade Break XSlope (%)	0.0	
	J. L.			Yes	Ramp XSlope (%)	0.5				
A C A MEL				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
- 19 - 19				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
Mar 5	and the second second	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
DEED.				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
5. 133 A				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
6	- Elite			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
8	-	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	an Am			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
ast 1 a	it da			N/A	Painted X Walk1?	No		Road Slope (%)	6.7	
Street 1 Name TUC	CKASEEGEE RD				X Walk 1 Direction	To SW		Road X Slope (%)	0.6	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	6.7	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.6	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	23.3	

