

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.0

0.9

N/A

Good

Main Street: LAGO VISTA CT Cross Street: N/A Intersection ID: 10029903 Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 34B410314AB3 Ramp Type: Perp **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

47.0

47.0

N/A

No

To E

N/A

1.6

0.9

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



LAGO VISTA CT Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Compli	iance	Description
Remove & Replace Entire Ramp.	N/A	Ramp	Length (in)
· ·	No	Ramp	Width (in)
	N/A	Flare	Гуре LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Γraversable L⅂
	N/A	Landin	ig Length (in)
Surveyor Notes:	N/A	Landin	g Width (in)
N/A	N/A	Landin	g Slope (%)
	N/A	Landin	g X Slope (%
	N/A	Landin	g Curb? (Y/N
	N/A	Share	d Landing?
PROW/ADA:	N/A	Gutter	Ponding?
Not Found, R304.5.1	N/A	Gutter	Lip Ht (in)
	N/A	Painte	d X Walk1?
		X Wall	1 Direction
	N/A	X Wall	c 1 Width (in)
		X Wall	(1 Slope (%)
		X Wall	x 1 X Slope (%
	N/A	Ramp	inside XWalk
		Road	Slope (%)



Total Cost:







N/A

1850.00