

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9316	Main Street: KARENSTONE_DR			Cross Street: THE_PLAZA				Location:	SE
ADA ID: 3513E7600814	Ramp Ty	ype: BlendTrans1	Initial I	itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	6.	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	72.0	Yes	BlendTrans Slope (%)	3.3
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	1.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
A STATE				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
This				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		5		N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
d.				N/A	Shared Landing?	N/A		Dwe enset (iii)	10/4
	(e)	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Page 6			N/A	•	N/A		,	N/A
and the second	the second se	Not Found, R304.5.1		N/A	Gutter Lip Ht (in) Painted X Walk1?			Gutter X Slope (%) Painted X Walk2?	N/A N/A
				N/A		No T- OW			
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	KARENSTONE DR				X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.6		Clear Space?	N/A
					Road X Slope (%)	1.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

20.5