## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53235	Main Str	eet: EVERGREEN_DR	Cross Stre	ss Street: DOLLY_MADISON_RD				Location:	SE
ADA ID: 35C340C483F1	Ramp Ty	Ramp Type: BlendTrans1			Fail Overall Co	ce: N	o Severity Score:	10	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:	<u>Co</u>	Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp W	/ith N/A	A Ra	amp Length (in)	73.5	Yes	BlendTrans Slope (%)	3.1
		Two New Directional Ramps or	No	Ra	amp Width (in)	47.0	Yes	BlendTrans XSlope (%)	3.9
		Equivalent.	N/#	A Fla	are Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	A Fla	are Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
AND B			N/A	A Fla	are Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
S. S.			N/#	La	inding Length (in)	N/A	N/A	DWS Provided?	N/A
TITLE		Surveyor Notes:	N/#	La	Inding Width (in)	N/A	N/A	DWS Contrast?	N/A
		ASP UNDER CONSTRUCTION	N/#	La	inding Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	La	Inding X Slope (%)	N/A	N/A	DWS Full Width?	N/A
to The loss			N/#	La	Inding Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/#	Sh	nared Landing?	N/A			
		PROW/ADA:	N/#	Gi	utter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1	N/A	Gu	utter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/#	A Pa	ainted X Walk1?	No	N/A	Painted X Walk2?	N/A
	-			Х	Walk 1 Direction	To N		X Walk 2 Direction	N/A
	- III- O			Х	Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	EVERGREEN DR			Х	Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None			Х	Walk 1 X Slope (%)	5.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/#	A Ra	amp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A			Ro	oad Slope (%)	5.4		Clear Space?	N/A
				Ro	oad X Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
			N/#	An An	ny Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 320	00.00	Ob	ostruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

16.2