

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25897	Main Str	Main Street: CASTLEKEEP_RD			Cross Street: TIMBERCREST_CR				NE
								Location:	
ADA ID: 362443B0703C Ramp Type: Directional1		Initial	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	No.	Possible Solutions:		Compliance Description			Data Compliance Description		
	All Contractions	Remove & Replace Entire Ran	ıp.	N/A	Ramp Length (in)	62.0	N/A	Grade Break?	N/A
A CARLEN AND AND AND AND AND AND AND AND AND AN	A. 5 242			Yes	Ramp Width (in)	61.0	N/A	Grade Break Slope (%)	0.0
and the second second				Yes	Ramp Slope (%)	5.6	N/A	Grade Break XSlope (%)	0.0
	×/	1		No	Ramp XSlope (%)	3.3			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	A CARLER FOR			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	A NOR	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
DATA CARD AL STA		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	Mr. Al			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
E The				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	TRAD .	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	A 93	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	1 her 1			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
A A A	X			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
and the second of the				N/A	Painted X Walk1?	No		Road Slope (%)	10.2
Street 1 Name TIMB	BERCREST CR				X Walk 1 Direction	To S		Road X Slope (%)	0.4
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	10.2	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	2.6

