cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28913 Main Street: ELIZABETH_COLLINS_BV				Street:	SPRINGBANK_LN	Location:	NW		
ADA ID: 36A148657A	7A59 Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	46.25
	Codes/Mitigation Info		Field Measurements/Component Compliance						
		Possible Solutions:						ompliance Description Data	
2-pp		Remove & Replace Curb Ram	Nith	N/A	Ramp Length (in)	63.0	1	Ramp Slope (%)	10.7
		Two New Directional Ramps or		No	Ramp Width (in)	47.0		Ramp XSlope (%)	7.3
		Equivalent.		N/A	Flare Type LT		N/A	Flare Type RT	N/A
F. CRIN				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
The Participant is the				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
2 3 12				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
AT AT A		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
8				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
4- 10	ME AV E			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
O COL	the states			N/A	Shared Landing?	N/A		ζ, γ	
THE REPUT		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Fall ELERAL	States 1	R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ELIZABETH COLLINS BV	_			X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	3.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.4		X Walk 2 X Slope (%)	1.6
Street 2 Name	SPRINGBANK LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.8	N/A	Clear Space?	N/A
					Road X Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1							1		

Yes Surface Condition? (G/P)

Good





