cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

3.2

Intersection ID: 19296 Main Street: MEADOWOOD_LN Cross Street: PROVIDENCE_RD Location:							014	
Intersection ID: 19296 Main S	296 Main Street: MEADOWOOD_LN		Cross Street: PROVIDENCE_RD				SW	
ADA ID: 36BD51ADBAC0 Ramp	D: 36BD51ADBAC0 Ramp Type: ParaDiag		nitial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	42.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
E E E	Possible Solutions:	Com	Compliance Description Data		Compliance Description		Data	
	Remove & Replace Curb Ramp W	/ith N/A	Ramp Length LT (in)	69.0	N/A	Ramp Length RT (in)	62.0	
	Two New Directional Ramps or Equivalent.	No	Ramp Width LT (in)	35.0	No	Ramp Width RT (in)	33.0	
		No	Ramp Slope LT (%)	8.6	Yes	Ramp Slope RT (%)	7.1	
		Yes	Ramp XSlope LT (%)	0.2	No	Ramp XSlope RT (%)	5.4	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	-	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	Surveyor Notes:	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	PROW/ADA:	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	R304.5.1, R304.3.2, R304.5.3	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	,,		X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
, and the second second			X Walk 1 Slope (%)	6.9		X Walk 2 Slope (%)	5.0	
Street 1 Name PROVIDENCE R)		X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	9.1	
Stop Condition-Street 1 Non	9	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Street 2 Name MEADOWOOD L	4		Road Slope (%)	4.9	N/A	Clear Space?	N/A	
Stop Condition-Street 2 StopSig	1		Road X Slope (%)	8.1	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
			Obstruction Type			Storm Grate/Utility Type		
	Total Cost: \$ 320	00.00		N/A			N/A	
					Yes	Surface Condition? (G/P)	Good	

