

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: N/A Main Street: BALLANTYNE VILLAGE DR Cross Street: N/A Location: NE ADA ID: 372CEDAB8BE4 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance



Street 1 Name **ENTRANCE** Stop Condition-Street 2 StopSign Street 2 Name **BALLANTYNE VILLAGE WY** Stop Condition-Street 1 None

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: 3200.00

| Compliance Description |                       | Data  | Compliance |       | Description           | Data |
|------------------------|-----------------------|-------|------------|-------|-----------------------|------|
| N/A                    | Ramp Length (in)      | 80.0  | No         | Ramp  | Slope (%)             | 10.6 |
| No                     | Ramp Width (in)       | 38.0  | No         | Ramp  | XSlope (%)            | 2.1  |
| N/A                    | Flare Type LT         | N/A   | N/A        | Flare | Type RT               | N/A  |
| N/A                    | Flare Slope LT (%)    | N/A   | N/A        | Flare | Slope RT (%)          | N/A  |
| N/A                    | Flare Traversable LT? | N/A   | N/A        | Flare | Traversable RT?       | N/A  |
| N/A                    | Landing Length (in)   | N/A   | N/A        | DWS   | Provided?             | N/A  |
| N/A                    | Landing Width (in)    | N/A   | N/A        | DWS   | Contrast?             | N/A  |
| N/A                    | Landing Slope (%)     | N/A   | N/A        | DWS   | Length (in)           | N/A  |
| N/A                    | Landing X Slope (%)   | N/A   | N/A        | DWS   | Full Width?           | N/A  |
| N/A                    | Landing Curb? (Y/N)   | N/A   | N/A        | DWS   | Offset (in)           | N/A  |
| N/A                    | Shared Landing?       | N/A   |            |       |                       |      |
| N/A                    | Gutter Ponding?       | N/A   | N/A        | Gutte | r Slope (%)           | N/A  |
| N/A                    | Gutter Lip Ht (in)    | N/A   | N/A        | Gutte | r X Slope (%)         | N/A  |
| N/A                    | Painted X Walk1?      | No    | N/A        | Paint | ed X Walk2?           | No   |
|                        | X Walk 1 Direction    | To NW |            | X Wa  | lk 2 Direction        | To S |
| N/A                    | X Walk 1 Width (in)   | N/A   | N/A        | X Wa  | lk 2 Width (in)       | N/A  |
|                        | X Walk 1 Slope (%)    | 6.5   |            | X Wa  | lk 2 Slope (%)        | 3.6  |
|                        | X Walk 1 X Slope (%)  | 4.1   |            | X Wa  | lk 2 X Slope (%)      | 5.3  |
| N/A                    | Ramp inside XWalk1?   | N/A   | N/A        | Ramp  | inside XWalk2?        | N/A  |
|                        | Road Slope (%)        | 0.3   | N/A        | Clear | Space?                | N/A  |
|                        | Road X Slope (%)      | 5.2   | N/A        | Clear | Space to XWalk (in)   | N/A  |
| N/A                    | Any Obstructions?     | N/A   | N/A        | Storm | Grate/Utility Hazard? | N/A  |
|                        | Obstruction Type      |       |            | Storm | Grate/Utility Type    |      |
|                        |                       | N/A   |            |       |                       | N/A  |
|                        |                       |       | Yes        | Surfa | ce Condition? (G/P)   | Good |
| -                      |                       |       |            |       |                       |      |





