

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23929	Main Str	Main Street: BROADWATER_LN			Cross Street: STEPHENDALE_DR				NW	
ADA ID: 395B87703BC3	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance:			o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	100	Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	50.0	N/A	Grade Break?	N/A	
	AM B/S			No	Ramp Width (in)	42.0	N/A	Grade Break Slope (%)	0.0	
	3			Yes	Ramp Slope (%)	6.2	N/A	Grade Break XSlope (%)	0.0	
				No	Ramp XSlope (%)	6.1				
	STAN A			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
a to		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
STATISTICS IN STATISTICS	1 ASTR			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
A CONTRACT OF	Que &			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
The second second	LOB CONTRACT			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
man the second s		R304.5.1, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
ACTIVAL STATE				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
A CONTRACTOR AND A CONTRACTOR				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	Contraction / /			N/A	Painted X Walk1?	No		Road Slope (%)	2.3	
Street 1 Name	BROADWATER LN	-			X Walk 1 Direction	To E		Road X Slope (%)	1.8	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.8	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	11.9	

