

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

9.8

Intersection ID: 10014252	Main Str	eet: PARKWOOD_AV	Cross St	Cross Street: N/A					NW	
ADA ID: 39C4B6914540	Ramp Type: Para			Initial Pass/Fail: Fail Overall Compliance: No					13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Comp	liance Description	Data	Comp	liance Description	Data	
	6.7	Remove & Replace Entire Ram	Э.	N/A	Ramp Length LT (in)	76.0	N/A	Ramp Length RT (in)	81.0	
TIM				Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.0	
			I	No	Ramp Slope LT (%)	10.9	No	Ramp Slope RT (%)	9.4	
				Yes	Ramp XSlope LT (%)	1.9	No	Ramp XSlope RT (%)	2.5	
The second second	110		I	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	. / ///		I	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
et al a second	1 Mi	Surveyor Notes:	I	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
the second se	11 1	N/A	I	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Sold Sold Sold Sold Sold Sold Sold Sold	1 <u>6.</u>		I	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	1 7 .		I	N/A	Shared Landing?	N/A				
A A A A A A A A A A A A A A A A A A A			I	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		PROW/ADA:	I	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	100	R304.3.2, R304.5.3	I	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	HE .				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
a a	CON POS		I	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
1 1 Alton 1 h	CAR CAN				X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A	
Street 1 Name	PARKWOOD AV				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A	
Stop Condition-Street 1	None		I	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
					Obstruction Type			Storm Grate/Utility Type		
		Total Cost: \$	1600.00			N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

