cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5207	Main Street: HUBBARD_RD			Cross	Cross Street: HUBBARD_WOODS_RD				Location:	E
ADA ID: 39EDE8A056DB	Ramp Type: Perp			Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	37.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	C. Martin	Possible Solutions:						Compliance Description		Data
A A A A A A A A A A A A A A A A A A A	AL .	Remove & Replace Ent	tire Ramr).	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	10.2
CARLE AND A SHA				-	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	9.8
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E F					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	121				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ES/	C Stand				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Allon the	A 27	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
SARD	A state				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	- Alter				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A A A A A A A A A A A A A A A A A A A					N/A	Shared Landing?	N/A			
and the second second	10-	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A State of the second s	CALLY.	Not Found, R304.2.2, R	304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	R. I.				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	the las					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
	A June				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name HUBBARD WOODS RD					X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good



