

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025598Main Street: E_WOODLAWN_RDCross Street: N/ALocation:SWADA ID: 3A23EFFA24F1Ramp Type: ParaInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



The condition of the property of the condition of the con	
Street 1 Name	ENTRANCE
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

1 099ibic Ocidiioii	
Possible Solutions:	С
Remove & Replace Entire Ramp.	N
·	Y
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N.
R304.3.2, R304.5.3	N
	N

Total Cost:	\$ 1600.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length LT (in)	62.0	N/A	Ramp Length RT (in)	70.0	
Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.0	
No	Ramp Slope LT (%)	8.5	Yes	Ramp Slope RT (%)	5.1	
No	Ramp XSlope LT (%)	2.4	No	Ramp XSlope RT (%)	3.5	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	6.7		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
			N/A	Curb Slope (%)	18.4	





