cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45302	Main Street: CINDY_CREEK_LN			Cross Street: CINDY_PARK_DR				Location:	NE
ADA ID: 3A62AB45DB8A	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	17.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Part Martin	Possible Solutions:		Compliance Description Da			ata Compliance Description		Data
		Remove & Replace Curb F	Ramp With	N/A	Ramp Length (in)	47.0	Yes	BlendTrans Slope (%)	0.3
		Two New Directional Ram	-	No	Ramp Width (in)	35.0	Yes	BlendTrans XSlope (%)	0.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 3 4			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A ANDY CRE	EK LIN	NO LT SW		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6. 6.	a mail			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	him	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		·····, ·····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	and all				X Walk 1 Direction	To W		X Walk 2 Direction	To S
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name CIND	Y PARK DR				X Walk 1 Slope (%)	6.5		X Walk 2 Slope (%)	6.6
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	5.2
Street 2 Name CINDY	CREEK LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	0.0		Clear Space?	N/A
					Road X Slope (%)	9.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

5.8