

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46817Main Street: ARBOR_VISTA_DRCross Street: HOLM_OAK_PLLocation: NWADA ID: 3AA0BD43BBEBRamp Type: PerpDiagInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 30

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

ARBOR VISTA DR None HOLM OAK PL StopSign

Possible Solution
Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.
Surveyor Notes:
N/A
PROW/ADA:
Not Found, R304.5.1, R304.2.2

Total Cost: \$ 3200.00

Fleid Measurements/Component Compilance						
Compliance Description		Data	Comp	Compliance Description		
N/A	Ramp Length (in)	43.5	No	Ramp Slope (%)	10.2	
No	Ramp Width (in)	32.5	Yes	Ramp XSlope (%)	0.6	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	X Walk 1 Direction	To S		X Walk 2 Direction	ТоЕ	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	0.1	
	X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	2.3	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	1.6	N/A	Clear Space?	N/A	
	Road X Slope (%)	2.4	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





