

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

8.0

Intersection ID: 28006	Main Str	Cross St	Cross Street: PROVIDENCE_RD					NW		
ADA ID: 3AD1464D8051	Ramp Ty	Initial Pas	ss/Fa	ail: Fail Overall C	o Severity Score:	13.75				
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
ALC AL		Possible Solutions:	(	Compliance Description Data Comp			liance Description	Data		
CITANOFLOT LIN	FROME INC.	Remove & Replace Curb Ramp V	Vith I	N/A	Ramp Length LT (in)	54.0	N/A	Ramp Length RT (in)	62.5	
		Two New Directional Ramps or		Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0	
		Equivalent.	1	No	Ramp Slope LT (%)	8.4	Yes	Ramp Slope RT (%)	5.9	
			١	res	Ramp XSlope LT (%)	2.0	No	Ramp XSlope RT (%)	2.2	
			1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
			1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		Surveyor Notes:	1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A		()		
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		PROW/ADA:		I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		R304.3.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
		1304.3.2, 1304.3.3			X Walk 1 Direction	To S		X Walk 2 Direction	To E	
			N	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
					X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	0.9	
Street 1 Name	CHANCELOT LN				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	0.1	
Stop Condition-Street 1	StopSign		N	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Street 2 Name	PROVIDENCE RD				Road Slope (%)	0.7	N/A	Clear Space?	N/A	
Stop Condition-Street 2	None				Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A	
			,	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
			'	ΨA	Obstruction Type	17/4		Storm Grate/Utility Type	11/2	
		Total Cost: \$ 32	200.00			N/A		etern orato/ounty type	N/A	
		τοταί σοστ. ψ υζ				17/4	Yes	Surface Condition? (G/P)	Good	
							165		3000	

