cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11066	6 Main Street: BRIARGROVE_DR				Street:	MENDHAM_DR	Location:	NE		
ADA ID: 3CFE9B120384	Ramp T	Ramp Type: Directional1			Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	7.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:				Comn	liance Description	liance Description	Data			
		Remove & Replace Entire R			N/A	Ramp Length (in)	36.0	1	Grade Break?	N/A
The	18 1000000000	Remove & Replace Ent		p.	Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0
and the local of		Remove & Replace Out			Yes	Ramp Slope (%)	1.4	N/A	Grade Break XSlope (%)	0.0
1					No	Ramp XSlope (%)		IN/A	Glade bleak ASiope (70)	0.0
	L.					,	4.4			N1/A
PD PD		4			N/A N/A	Flare Type LT	N/A N/A	N/A N/A	Flare Type RT	N/A N/A
ANARGA E		Cumunum Natan				Flare Slope LT (%)			Flare Slope RT (%)	
NOVE S		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
R B C		N/A			Yes	Landing Length (in)	59.0	Yes	DWS Provided?	Yes
					Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
the second	EFEIII				Yes	Landing Slope (%)	0.0	Yes	DWS Length (in)	24.0
L.	The second second				No	Landing X Slope (%)	2.8	No	DWS Full Width?	No
	S. BE	PROW/ADA:			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	0.0
		R304.5.3, R305.1.4, R30	5.2, R3	04.5.4	N/A	Shared Landing?	No	No	DWS Offset RT (in)	61.0
					Yes	Gutter Ponding?	No	No	Gutter Slope (%)	6.0
					Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.7
	T				N/A	Painted X Walk1?	No		Road Slope (%)	3.0
Street 1 Name	BRIARGROVE DR					X Walk 1 Direction	To S		Road X Slope (%)	1.8
Stop Condition-Street 1	None					X Walk 1 Width (in)	N/A		Clear Space?	Yes
Street 2 Name	N/A					X Walk 1 Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	1.8	Yes	Storm Grate/Utility Hazard?	No
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					Yes	Any Obstructions?	No			N/A
		Total Cost:	\$	2350.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
			Ŧ	_,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			N/A	N/A	Curb Slope (%)	17.5

