

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

34.0

71.0

10.4

2.6

5.4

2.0

N/A

Intersection ID: N/A Main Street: CENTRAL AV **Cross Street: TAMPLE LN** Location: NE Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: 3D353813ADAA** Ramp Type: Combination2 Severity Score: 31.25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

52.0

71.0

2.9

2.0

71.0

35.5

N/A

No

To W

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign Stop Condition-Street 1 **TEMPLE LN** Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes Yes N/A No Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1 N/A N/A N/A N/A N/A N/A





Total Cost:



		X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	R9753
1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
1.00				N/A	Any Obstruction?	N/A
THE PERSON NAMED IN COLUMN					Obstruction Type	
	-					N/A
				N/A	Storm Grate/Utility Hazard?	N/A
					Storm Grate/Utility Type	IVA
4						N/A
	1 PHE			Yes	Surface Condition? (G/P)	Good
					Curb Slope (%)	14.1