

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14281	Main Str	Main Street: E_KINGSTON_AV			Cross Street: LYNDHURST_AV				N	
							Location:			
ADA ID: 3E9EEF8CE9A5 Ramp Type: Directional1		Initial	Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	A HE AL	Possible Solutions:		Compliance Description			Data Compliance Description			
No la Est		Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	88.0	N/A	Grade Break?	N/A	
	10			Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
	24 / / .			No	Ramp Slope (%)	10.7	N/A	Grade Break XSlope (%)	0.0	
				No	Ramp XSlope (%)	4.0				
1	AS ANTAL			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
A A A A A A A A A A A A A A A A A A A		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
L L	Ella Des	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	10 10 · ·			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
E CARA E E	Ball A			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
GIO	in War	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	Ne le .	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	ALL A			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
EX CR.	and the set			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	A Star A Star			N/A	Painted X Walk1?	No		Road Slope (%)	2.6	
Street 1 Name	LYNDHURST AV				X Walk 1 Direction	To SE		Road X Slope (%)	4.2	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.2	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	7.6	

