

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24896 Main Street: GADWALL_CT Cross Street: KING_EIDER_DR Location: NE **Overall Compliance: No** ADA ID: 3EC8328661BE Ramp Type: Directional1 Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW
Street 1 Name	GADWALL CT
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Ston Condition-Street 2	N/A

Possible Solutions:
Remove & Replace Entire Ramp.
Surveyor Notes:
N/A
PROW/ADA:
R304.5.3

		N/A
		N/A
		N/A
PROW/ADA:		N/A
R304.5.3		N/A
		N/A
		N/
		N/A
		N/A
		N/A
Total Cost:	\$ 1600.00	

Field Measurements/Component Compliance									
Comp	liance Description	Data	Comp	liance	Description	Data			
N/A	Ramp Length (in)	21.0	N/A	Grad	e Break?	N/A			
Yes	Ramp Width (in)	48.0	N/A	Grad	e Break Slope (%)	0.0			
Yes	Ramp Slope (%)	1.4	N/A	Grad	e Break XSlope (%)	0.0			
No	Ramp XSlope (%)	5.5							
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0			
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A			
N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A			
N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A			
N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A			
N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A			
N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A			
N/A	Gutter Ponding?	0.0	N/A	Gutte	er Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutte	er X Slope (%)	N/A			
N/A	Painted X Walk1?	No		Road	Slope (%)	3.2			
	X Walk 1 Direction	To S		Road	X Slope (%)	3.0			
	X Walk 1 Width (in)	N/A	l	Clear	Space?	N/A			
	X Walk 1 Slope (%)	3.2	N/A	Clear	Space to XWalk (in)	N/A			
	X Walk 1 X Slope (%)	3.0	N/A	Storn	n Grate/Utility Hazard?	N/A			
N/A	Ramp inside XWalk1?	N/A		Storn	n Grate/Utility Type				
N/A	Any Obstructions?	N/A				N/A			
	Obstruction Type		Yes	Surfa	ce Condition? (G/P)	Good			
		N/A	N/A	Curb	Slope (%)	31.8			





