cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49134	tersection ID: 49134 Main Street: AMESBURY_HILL_DR Cr				CEMKEY_WAY_CT	Location:	NW			
ADA ID: 3F1CA29A2520	A2520 Ramp Type: BlendTrans1 Init			al Pass/Fail: Fail Overall Compliance: No			Severity Score:	21.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:					bliance Description Data			
		Remove & Replace Curb Ra	mn With	N/A	Ramp Length (in)	48.5	Yes	BlendTrans Slope (%)	3.5	
		Two New Directional Ramps		No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	5.1	
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
Server and the server of the		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
CENKEY WAY OT &		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
े हैं।				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
(1)	a series of the		JUT.U.U	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
3	the second second				X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	CEMKEY WAY CT	-			X Walk 1 Slope (%)	7.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	4.5		Clear Space?	N/A	
					Road X Slope (%)	7.3	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
		·			51	N/A			N/A	
1							Yes	Surface Condition? (G/P)	Good	







No

Curb Slope (%)

5.2