

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5124	Main Street: GIBBON_RD			Cross	Cross Street: OLD_STATESVILLE_RD				Location: S		
ADA ID: 3F4D20F19D92	Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance			nce: N	ce: No Severity Score: 33.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
Possible Solutions:				Compliance Description Data Compliance Description Data							
	17.0	Remove & Replace Entire		<b>.</b>	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	13.7	
La b		Remove & Replace Ent	ire Kailij	μ.	No	Ramp Width (in)	44.0	Yes	Ramp XSlope (%)	0.7	
	LIND	ii			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
16	<u>ь</u>	2			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
the second	e <mark>s</mark>				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
6. S	CIEBON DD	5			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	A State A	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
States and a little states	IN AND AND	6 4			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	11 32 31				N/A	Shared Landing?	N/A		2		
	A LANK	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1, R	201 2 2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	A The last		504.2.2		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
1 11 Alter		à			N/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	OLD STATESVILLE RD					X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					, Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	





Yes

Surface Condition? (G/P)

Good