cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18366	Main Street: BRIARDALE_DR			treet:	SHARON_FOREST_D	Location:	SE			
ADA ID: 3FF62505C912	2 Ramp Ty	Ramp Type: BlendTrans2			itial Pass/Fail: Pass Overall Compliance: No				0.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	TARON PORTESIC DIS	Possible Solutions:		<u>-</u>				liance Description		
11 80.8		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	2.7	
		Two New Directional Ramps or	V ICII	Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	3.9	
		Equivalent. Remove & Replace Gutter.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped	
120 1				N/A	Flare Slope LT (%)	•		Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
the states and the states				N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes	
		Surveyor Notes: N/A		N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes	
				N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0	
PROW/ADA: Not Found, R304.5.3				N/A	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes	
				N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0	
				N/A	Shared Landing?	No				
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.9	
				Yes	Gutter Lip Ht (in)	0.0		Gutter X Slope (%)	3.3	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
AND BEA THE STATE	8 11- W				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
and the set	N N N S S				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	SHARON FOREST DR				X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	6.8	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	7.3		X Walk 2 X Slope (%)	2.1	
Street 2 Name	BRIARDALE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	StopSign				Road Slope (%)	2.5		Clear Space?	Yes	
					Road X Slope (%)	8.0	N/A	Clear Space to XWalk (in)	N/A	
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost: \$ 39	950.00		Obstruction Type			Storm Grate/Utility Type		
		· · ·				N/A		· -····, · ·/··	N/A	
							Yes	Surface Condition? (G/P)	Good	
								()		







No

Curb Slope (%)

10.6