

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6143	Main Street: COREOPSIS_RD				Street.	YARROW_RD	Location:	NW			
ADA ID: 41E9DB7C780B Ramp Type: Perp			Initial	Pass/Fa	ail: Fail Overall C	o Severity Score:	37.5				
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description				
	11 - Chill Pondi	Remove & Replace Entire	Ramp	<b>)</b> .	N/A	Ramp Length (in)	51.0	No	Ramp Slope (%)	11.8	
A ALCONTIN		-			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	8.9	
	alog for a stra				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Non-de All				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
and the second of the	11	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
COREOPSISIR				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
<u>6</u>					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
L CONTRACTOR		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Not Found, R304.2.2, R304.5			4.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	YARROW RD					X Walk 1 Slope (%)	6.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	6.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

Yes Surface Condition? (G/P)

Good

