

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

12.3

Intersection ID: N/A	Main Street: TWITTER_LN			Cross Street: ROCKY_RIVER_RD				Location:	NW
ADA ID: 422AA6EDD370	D370 Ramp Type: Para			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A SA SA ANA ANA ANA ANA		Possible Solutions:		Compliance Description Dat			a Compliance Description		Data
		Remove & Replace Entire R	Ramp.	N/A	Ramp Length LT (in)	63.0	N/A	Ramp Length RT (in)	59.0
	3			Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	59.0
				No	Ramp Slope LT (%)	8.5	Yes	Ramp Slope RT (%)	1.1
				Yes	Ramp XSlope LT (%)	0.3	Yes	Ramp XSlope RT (%)	0.8
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
the second second				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the second secon	RT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A COM	I E			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A CONTRACTOR				N/A	Shared Landing?	N/A			
Charles and				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A		PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The Part of the second		R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	17 4				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	We the			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
I The second in a second	the Real and				X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	N/A
Street 1 Name	ROCKY RIVER RD	-			X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost:	\$ 1600.	00		N/A			N/A
							Yes	Surface Condition? (G/P)	Good

