

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25705	Main Street: REA_RD			eet:	SUNDANCER_LN	Location:	NW		
ADA ID: 42349410C22C	Ramp Ty	Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	1.25			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description			Data Compliance Description			Data
A LAND AND A LAND		Remove & Replace Entire Ramp	N	/ <b>A</b>	Ramp Length (in)	84.0	N/A	Grade Break?	N/A
	I I UK	· · · ·	Ye	es	Ramp Width (in)	70.0	N/A	Grade Break Slope (%)	0.0
/ · · · · · · · · · · · · · · · / / / /	I Marson		Ye	es	Ramp Slope (%)	0.7	N/A	Grade Break XSlope (%)	0.0
			N	0	Ramp XSlope (%)	3.8			
			N/	<b>/A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/	<b>/A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
SUNDANGER LIN - 5.		Surveyor Notes:	N/	<b>/A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	N/	<b>/A</b>	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
			N/	<b>/A</b>	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
			N/	<b>/A</b>	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
			N/	<b>/A</b>	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:	N/	<b>/A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	111 : A MARCE	R304.5.3	N/	<b>/A</b>	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
			N/	<b>/A</b>	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	1 Agent Star		N	/ <b>A</b>	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			N/	<b>/A</b>	Painted X Walk1?	No		Road Slope (%)	3.7
Street 1 Name S	SUNDANCER LN				X Walk 1 Direction	To S		Road X Slope (%)	1.4
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.4	N/A	Storm Grate/Utility Hazard?	N/A
			N/	<b>/A</b>	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			N	/ <b>A</b>	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	9.4





