

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Good

Yes

Intersection ID: N/A Main Street: E\_MARTIN\_LUTHER\_KING\_JR\_GBVss Street: S\_BREVARD\_ST Location: N

ADA ID: 42B7079C76EC Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

## Codes/Mitigation Info/P

1/20	
Street 1 Name	E MARTIN LUTHER KING JR BV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

/Possible Solution			Field Measurements/Component Compliance					
Possible Solutions:		Comp	liance Description	Data	Complia	nce Description	Data	
Remove & Replace Entire I	Ramp.	N/A	Ramp Length (in)	72.0	Yes F	Ramp Slope (%)	5.4	
•	•	Yes	Ramp Width (in)	48.0	No F	Ramp XSlope (%)	5.2	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
•		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To SW	2	X Walk 2 Direction	N/A	
		N/A	X Walk 1 Width (in)	144.0	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	8.0		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	2.2	2	X Walk 2 X Slope (%)	N/A	
		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A	N/A (	Clear Space?	N/A	
			Road X Slope (%)	N/A	N/A (	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
Total Cost:	\$ 1850.0	00	Obstruction Type			Storm Grate/Utility Type		
				N/A	ı		N/A	





