cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8566	ersection ID: 8566 Main Street: HILDEBRAND_ST			Cross Street: TAYLOR_AV				Location: E	
ADA ID: 433CCE48B9D9 Ramp Type: Directional1		Ini	Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	and the set	Possible Solutions:		Compliance Description			Data Compliance Description Data		
	Detter . e	Remove & Replace Entire R	amp.	N/A	Ramp Length (in)	80.0	N/A	Grade Break?	N/A
		· · · ·	•	No	Ramp Width (in)	36.0	N/A	Grade Break Slope (%)	0.0
				No	Ramp Slope (%)	11.5	N/A	Grade Break XSlope (%)	0.0
				Yes	Ramp XSlope (%)	1.6			
	- 19/51			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	19 Star	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	-	NO CURB LINE		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
S COMILDEBRA	ND_ST			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	Frank T			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	Marker 1			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
Jack Jack	Carried and	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	Server A	R304.5.1, R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	Alleh at a f	, , , , , , , , , , , , , , , , , , ,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	HAR MA L			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	W La Sull			N/A	Painted X Walk1?	No		Road Slope (%)	0.5
Street 1 Name	TAYLOR AV				X Walk 1 Direction	To W		Road X Slope (%)	4.4
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.4	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.0	00	Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	0.0

