cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpotion ID: 52444	Main Of		0	oo Street				Location	NI\A/
Intersection ID: 52441	Main Street: WOODWARD_AV			Cross Street: BENDING_BIRCH_PL			Location:	NW	
ADA ID: 434272237B31	7B31 Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire Ra	mp.	N/A	Ramp Length (in)	76.0	N/A	Grade Break?	N/A
A ALL AND		-	•	Yes	Ramp Width (in)	68.5	N/A	Grade Break Slope (%)	0.0
				No	Ramp Slope (%)	9.2	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	4.3			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
The second secon		Surveyor Notes:		N/A	Flare Traversable L	T? N/A	N/A	Flare Traversable RT?	N/A
AN L		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	6 B			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
the second				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
6.				N/A	Landing X Slope (%) 0.0	N/A	DWS Full Width?	N/A
	Doctores Change	PROW/ADA:		N/A	Landing Curb? (Y/N) N/A	N/A	DWS Offset LT (in)	N/A
	1. 10	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	a a a a a a a a a a a a a a a a a a a	,		N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A	
the attent to the second	A CALLER MANY			N/A	Painted X Walk1?	No		Road Slope (%)	5.9
Street 1 Name	BENDING BIRCH PL				X Walk 1 Direction	To E		Road X Slope (%)	0.5
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	5.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%	6) 0.5	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk	1? N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00)	Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	5.2

