cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44006	Main Street: DEMAINE_DR			Cross	Street:	ELROSE_PL	Location:	Е		
ADA ID: 436A534B79B4	Ramp Ty	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	1922	Possible Solutions:			Compliance Description			Data Compliance Description		
	ALUTE DE	Remove & Replace (Curb Ram	n With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	3.9
		Two New Directional	•		No	Ramp Width (in)	45.0	No	BlendTrans XSlope (%)	3.1
		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	NO 3				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
leg G		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Charles and a second	> 5m				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A				
120		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.	1 R304 5 ⁴	3	N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A	
	Not i ound, 1004.0.	1, 1004.0.	5	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	DEMAINE DR	-				X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	4.5
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	2.7
Street 2 Name	ELROSE PL				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None					Road Slope (%)	0.6		Clear Space?	N/A
						Road X Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		-				,,	N/A			N/A
								•		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.8