

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12078	Main Str	eet: MARLOWE AV	Cross	Street <sup>.</sup>	HIGHLAND_ST	Location:	NW		
ADA ID: 439B49AA54F5 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A A A A A A A A A A A A A A A A A A A		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.2
A DE CONTRACTOR	Batter Mar			No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	5.1
A Manual 1				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	MA .			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E E	A DE CONTRACTOR			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	At a shirt	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<b>5</b>	a suborn	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
MARLOWE AV 10	J TORONT IS A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1 - 1 states M			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
alway and the				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A Frank	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A State			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	The second				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
	1 700			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HIGHLAND ST				X Walk 1 Slope (%)	6.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

es Surface Condition? (G/P)

Good

