cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5916	on ID: 5916 Main Street: FAIRES_FARM_RD			Cross Street: HANBERRY_BV				Location:	S
ADA ID: 4660D135415D	Ramp Ty	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ran	np With	N/A	Ramp Length (in)	72.0	Yes	BlendTrans Slope (%)	3.9
		Two New Directional Ramps		No	Ramp Width (in)	46.5	Yes	BlendTrans XSlope (%)	0.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	A The			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Con March	1		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
al Filler to		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Russes and The Control of the Contro				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Not Found, R304.5.1				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	HANBERRY BV	-			X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	3.7
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	3.4
Street 2 Name	FAIRES FARM RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	3.5		Clear Space?	N/A
					Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

19.8