cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29355	Main Street: TETON_TL			Cross Street: ONEIDA_RD				Location:	Ν
ADA ID: 46BD12C39AA4	Ramp Type: BlendTrans1		Initial	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:					liance Description	Data	
		Remove & Replace Curb Ram	o With	N/A	Ramp Length (in)	45.5	Yes	BlendTrans Slope (%)	2.5
		Two New Directional Ramps o		Yes	Ramp Width (in)	128.0	No	BlendTrans XSlope (%)	8.0
		Equivalent.	-	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A CARACTER AND A CARACTER ANTE ANTE ANTE ANTE ANTE ANTE ANTE ANTE		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
20	Con a la			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
G. WERDLE	为学上:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A Starte			N/A	Shared Landing?	N/A			
	A State of the second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
a state the second	Star int	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Painted X Walk2?	N/A
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
The second second second					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name T	ETON TL	-			X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	5.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	. c N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	5.1		Clear Space?	N/A
					Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

25.6