

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|   |                         |   |                        |
|---|-------------------------|---|------------------------|
| Intersection ID: 5928                   | Main Street: CRANDON_DR | Cross Street: PEACHTREE_RD              | Location: NW           |
| ADA ID: 48760D01204F                    | Ramp Type: Combination1 | Initial Pass/Fail: Fail                 | Overall Compliance: No |
| Severity Score: 22.5                    |                         |   |                        |
| Codes/Mitigation Info/Possible Solution |                         | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Remove & Replace Entire Ramp.  
Remove & Replace Sidewalk.**

Surveyor Notes:

**LT RP < 5%**

PROW/ADA:

**Not Found, R304.5.1, R304.5.3,  
R304.3.2**

Total Cost:

\$ 2200.00

| Compliance | Description              | Data | Compliance | Description                 | Data |
|------------|--------------------------|------|------------|-----------------------------|------|
| N/A        | Ramp Length LT (in)      | 39.0 | N/A        | Ramp Length RT (in)         | 74.0 |
| No         | Ramp Width LT (in)       | 47.0 | No         | Ramp Width RT (in)          | 47.5 |
| Yes        | Ramp Slope LT (%)        | 1.6  | No         | Ramp Slope RT (%)           | 10.3 |
| No         | Ramp XSlope LT (%)       | 3.5  | No         | Ramp XSlope RT (%)          | 2.1  |
| N/A        | Ramp Length (in)         | 48.0 | Yes        | Ramp Slope (%)              | 6.4  |
| Yes        | Ramp Width (in)          | 48.0 | Yes        | Ramp XSlope (%)             | 2.9  |
| N/A        | Flare Type LT            | N/A  | N/A        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)       | N/A  | N/A        | Flare Slope RT (%)          | N/A  |
| N/A        | Flare Traversable LT?    | N/A  | N/A        | Flare Traversable RT?       | N/A  |
| N/A        | Landing Length (in)      | N/A  | N/A        | DWS Provided?               | N/A  |
| N/A        | Landing Width (in)       | N/A  | N/A        | DWS Contrast?               | N/A  |
| N/A        | Landing Slope (%)        | N/A  | N/A        | DWS Length (in)             | N/A  |
| N/A        | Landing X Slope (%)      | N/A  | N/A        | DWS Full Width?             | N/A  |
| N/A        | Landing Curb? (Y/N)      | N/A  | N/A        | DWS Offset (in)             | N/A  |
| N/A        | Shared Landing?          | N/A  |            |                             |      |
| N/A        | Gutter Ponding?          | N/A  | N/A        | Gutter Slope (%)            | N/A  |
| N/A        | Gutter Lip Ht (in)       | N/A  | N/A        | Gutter X Slope (%)          | N/A  |
| N/A        | Painted X Walk1?         | No   | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction       | To S |            | X Walk 2 Direction          | N/A  |
|            | X Walk 1 Width (in)      | N/A  |            | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)       | 0.8  |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%)     | 3.7  |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?      | N/A  | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)           | 3.7  |            | Clear Space?                | N/A  |
|            | Road X Slope (%)         | 0.8  | N/A        | Clear Space to XWalk (in)   | N/A  |
|            |                          |      | N/A        | Any Obstruction?            | N/A  |
|            |                          |      |            | Obstruction Type            | N/A  |
|            |                          |      |            |                             |      |
|            |                          |      | N/A        | Storm Grate/Utility Hazard? | N/A  |
|            |                          |      |            | Storm Grate/Utility Type    | N/A  |
|            |                          |      |            |                             |      |
| Yes        | Surface Condition? (G/P) | Good |            |                             |      |
|            | Curb Slope (%)           | 27.0 |            |                             |      |

