


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7027	Main Street: TALUS_TRACE_LN	Cross Street: BEGONIA_DR	Location:	S
ADA ID: 48CAD5B65179	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 0

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	46.5	Yes	Ramp Slope (%)	7.3	
	Remove & Replace Gutter.		Yes	Ramp Width (in)	50.5	Yes	Ramp XSlope (%)	1.6	
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	5.1	Yes	Flare Slope RT (%)	6.6	
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes	
			Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes	
			Yes	Landing Width (in)	50.5	Yes	DWS Contrast?	Yes	
			Yes	Landing Slope (%)	1.6	Yes	DWS Length (in)	24.5	
			No	Landing X Slope (%)	2.1	Yes	DWS Full Width?	Yes	
Street 1 Name	Surveyor Notes:		N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.8	
	PROW/ADA:			Shared Landing?	No				
	Not Found, R304.5.3		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.5	
			Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.2	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A	
				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A	
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2				Road Slope (%)	N/A	N/A	Clear Space?	Yes	
	Street 2 Name		N/A	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
	Stop Condition-Street 1		N/A	Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type		